

Groove Measuring Tool

This handy gauge allows you to easily measure the angle of v-grooves both with or without an undercut.

To use simply loosen the thumb screw and insert the gauge into the v-groove holding the gauge so that it is perpendicular to the sheave surface. Slide the gauge until the measuring surfaces of the gauge firmly touch both sides of the v-groove and are squarely seated on it. During the inspection operation, the groove measuring tool has to be positioned at right angle to the groove to insure a proper measurement. While holding the gauge in the proper position in the v-groove tighten the thumb screw. The measuring gauge can then be removed from the v-groove and the measurement can be read.

