


Groove V Measuring Tool

Description

This simple angle-measuring tool will help you check traction sheaves for wear and tear, for example measuring the rope-grooves of worn traction sheaves. The tool is meant for measuring and checking V-grooves with or without undercut. It resembles a slide gauge and has a base with a scale of degrees. Hold the tool at right angle to the groove and shift the measuring limb to the opposite flange of the V-groove until it sits close to it. Angle-measuring tool, range 25°-70°.



Part No.

500000

Weight (lbs)

2 (1 kg)